

Abstract

5 calibration. A calibration face is carried out in which
calibration values are obtained. These values are stored and
then later used for adjustment of the values obtained from the
capacitors.